

**Diagram for Taper Boring with Vhu 36 head**

Example:  
 1. Draw a line from point "A" under the angle of  $a/2 = 30^\circ$ . In its cross-section with the line of the slide feed at 0.04 mm per revolution, deduct the spindle feed at 0.07 mm per revolution.  
 2. Draw a line connecting the spindle feed at 0.07 mm per revolution with point "B". In its cross-section with the spindle revolution line at 220 rpm, deduct the spindle feed at 15 mm per minute.


Calculation Formulas:  
 $\text{machine feed [mm per revolution]} = \text{slide feed [mm per revolution]} / \text{tg } a/2$   
 $\text{machine feed [mm per minute]} = \text{machine feed [mm per revolution]} \times \text{spindle rotation [rpm]}$

↑ machine rotation [rpm]

↑ slide feed [mm per revolution]

→ machine feed [mm per revolution]

↑ adjusting angle  $a/2$  [°]



**Diagram for Taper Boring with Vhu 56,80,110,125 or 160 heads**

Example:

1. Draw a line from point "A" under the angle of  $a/2 = 35^\circ$ . In its cross-section with the line of the slide feed at 0.05 mm per revolution, deduct the spindle feed at 0.072 mm per revolution.
2. Draw a line connecting the spindle feed at 0.072 mm per revolution with point "B". In its cross-section with the spindle revolution line at 220 rpm, deduct the spindle feed at 15.7 mm per minute.

Calculation Formulas:

machine feed [mm per revolution] = slide feed [mm per revolution] / tg  $a/2$   
 machine feed [mm per minute] = machine feed [mm per revolution] x spindle rotation [rpm]

↑ machine rotation [rpm]

↑ slide feed [mm per revolution]

→ machine feed [mm per revolution]

↑ adjusting angle  $a/2$  [°]